

Job No:	10005	Customer:	M100 : MOTORKRAFT
Priority:	2	Status:	Invoiced Serviceable
Cust Order:	123456	Cust Reference:	MOTOR 12345
Date Rec'd:	28/07/2003	Date Req'd:	01/08/2003
Delivery Note:	11001	Delivery Date:	28/07/2003
Invoice No:	12001	Invoice Date:	28/07/2003
Price:	500	Quantity :	1
Manufacturer:	BROOK HANSEN		
Type/Desc:	AC MOTOR		
Comments:	CLIENT THINKS BEARINGS NEED CHANGING		

**WORK DONE**

1. Collect Motor
2. Dismantle
3. Strip out Start and Run Windings
4. Completely Rewind
5. Remove old Bearings and fit new
6. Clean and Paint all Parts
7. Assemble and Test
8. Deliver Motor
- 9.
- 10.
- 11.
- 12.
- 13.
- 14.

**LABOUR COSTS**

Item	Who	Rate	T1	T2	T3	Cost	Margin %	Charge
1	JOHN	30	6.00	1.00	1.00	£261.60	120.00	£313.92
<b>Labour Totals:</b>			<b>6.00</b>	<b>1.00</b>	<b>1.00</b>	<b>£261.60</b>		<b>£313.92</b>

**SPARES COSTS**

Item	Who	Part	Qty	Cost Each	Margin %	Charge
1	JOHN	BEARINGS	2.00	£55.00	150.00	£165.00
<b>Spares Totals:</b>				<b>£110.00</b>		<b>£165.00</b>

**TOTAL COSTS: £371.60 £478.92**